



UNITED STATES DEPARTMENT OF COMMERCE
Patent and Trademark Office
ASSISTANT SECRETARY OF COMMERCE AND
COMMISSIONER OF PATENTS AND TRADEMARKS
P.O. Box 1450
Alexandria, VA 22313-1450

February 4, 2008

**Renner, Otto,
Boisselle & Sklar, LLP
19th Floor
1621 Euclid Avenue
Cleveland OH 44115-2191**

Patent No. : 6,717,212 B2
Inventor(s) : Dong-Hyuk Ju, et al.
Issued : April 6, 2004
For LEAKY, THERMALLY CONDUCTIVE
INSULATOR MATERIAL (LTCIM) IN
SEMICONDUCTOR-ON-INSULATOR (SOI)
STRUCTURE
Doc. No. F0522

To Whom It May Concern:

The Certificate of Correction issued on February 5, 2008, issued in error, in that error(s) was made in identifying the patent number and/or keying text/corrections, i.e.:

In the issued certificate of correction, the corrections are labeled incorrectly. The text to be amended at Claim 8, line 1, should be referred to as --Column 8,(claim 8) line 51-- in the printed patent. The 1050 form was submitted in claim number and line number format which was improper. The corrections are being converted into Column and line format of the printed patent. A superseding cofc will be issued to correct this error.

Therefore, a certificate of correction will be issued to correct (supersede) the Certificate of Correction containing error(s), made during preparation of the Certificate of Correction, as noted above.

No further response is required, from applicants (attorney). However, errors discovered by attorney, other than as noted and described above, should be noted on *a copy* of the Certificate of Correction that was issued in error, accompanied by a signed transmittal letter and submitted directed to this Branch.

Antonio Johnson
(703) 308-9390 ext. 111
For Cecelia Newman, Supervisor
Decisions & Certificates of Correction Branch
(703) 305-8309 / 703-308-9390 ext. 102
cbn